

to Chief Surveyors 29.6.18

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME

Sheers Lake Maurepas

Report

ClevelandNo. 159**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey \_\_\_\_\_

When due \_\_\_\_\_

100A-1 (Steel)

15K (Steel)


Cell DB 182' 429G. F.P.T. 386 Q.P.T. 536

FK. 6 BH. Cam. axed. P 28' B 66' Fry

The Certificate of Classification, to be endorsed  
"Cargo battens not fitted," and the same  
notation to be printed in the Register Book.

*M*  
1.7.18

It is concluded <sup>filler</sup> *filler* *8 1/2 x 23 1/8* *hull do*  
Surveyors should state if this is so



© 2021

Lloyd's Register  
Foundation.

W1510-0036