

Less
Less
E.
TON

250,7,13.

F.E.

Received by Chief Ship Surveyor 23. 10. 13 Received from Chief Ship Surveyor _____

VESSEL'S NAME Mt. Sc. (Old Motion Engine) "Linarco" Rpt. LH No. 14213

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 25-5 Depth "d" 7.25
 Framing: Table No. 3 page 9 Description Single angle as approved
 Longitudinal No. 2091
 Proportions Length 10.25
 Depth = _____
 Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ÷ 100 A.1 ("Steel") as recommended


÷ 100 A.1 ("Steel")

1 LH

N.B. Df 7' 5"

F.N. 4 BH C.m. Lays a & C. P

W.H.W.
23. 10. 13



© 2021
Metcalf & Partners
Lloyd's Register
Foundation