

1

Sent to Chief Surveyors 26. 11. 15.

Received from Chief Surveyors

27 NOV 1915

VESSEL'S NAME

s/s "Malaspina"

Report

Don.

No. 78342^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Screw shaft.

When due

8. 15.

The first biennial survey of this vessel's screw shaft became due in August. In reply to the usual notice the Deputy Minister of the Department of the Canadian Naval Service states that as this is a Government vessel it is not considered necessary to retain her class in Lloyd's Register.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof indicating that the class has been withdrawn at the Owners request.

Withdraw class.

Insert . . .

J.W.D.

26/11/15.

J.W.D.

C.B.K.



© 2020

Lloyd's Register
Foundation

W1519-0111