

Im.3.42

1

19 JUN 1942

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME BRITISH PRUDENCE. REPORT N.Yk. No. 42372

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE. When due

Subject to indented shell plates No.4
in 2nd strake below sheer, No.5 in 3rd strake below sheer
(p.s.) and No.3 in 1st strake below f'cle sheer (s.s.) being
dealt with at the Owners' convenience.

was
8.6.42



© 2019

Lloyd's Register
Foundation

W152-0123