

Sent to Chief Surveyors 7. 2. 16. Received from Chief Surveyors _____
 VESSEL'S NAME s/o "Minas." Report Lon. No. 78586^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Screw shaft When due 11. 15.

The first biennial survey of this vessel's screw shaft became due in November last.

The Owners now state that it is not their desire to comply with the requirements of this Society's Rules.

It is submitted that this vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof, indicating that the class has been withdrawn at the Owners' request.

Withdraw class.
 Insert . . .

E. B. Ke. *J. W. D.* *J. W. R. K.*
 7/2/16.



© 2020

Lloyd's Register
 Foundation