

to Chief Surveyors 19. 3. 23.

Received from Chief Surveyors

VESSEL'S NAME

S.K. "Merot"

Report

Lon.

No.

86444^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

Boiler

When due

10. 28.

Screw shaft due 3. 23.

The Boiler Survey became due in 10. 28. no part has been held.

The New Owners now state that they desire to have the vessel's class withdrawn.


It is submitted that the vessel's class be withdrawn & three dots inserted in lieu thereof, indicating that the vessel's class has been withdrawn from the Register Book at the Owners' request.

Withdraw class.

Insert ...

M

CMS



© 2020

Lloyd's Register
Foundation

W1526-0127