

5c, 12, 16.

F.E.

Received by Chief Ship Surveyor 10.6.18
Received from Chief Ship Surveyor
VESSEL'S NAME Steel "War Bunker" Rpt. Bel No. 7973

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. 62.95 Depth "d" 18.16
Framing: Table No. 3. page 11 Description Bulb Angle as appnd
Longitudinal No. 17915
Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.42}{1}$

Upper Deck Sheerstrake as appnd.
The Downton pump & Redg Anchor have been dispensed
with as appnd in Standard Vessels.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A-1 (Steel)

100 (Steel). 10000.
Cell D.B. 228' 5726 F.P.T. 1056. A.P.T. 2266
F.K. 7BH. 16 Can. Leguaces 129, Q 68' B 65' F 32'

This Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
to be printed in the Register Book.

M
10.6.18



© 2021

Lloyd's Register
Foundation

W1528 - 0062