

Received by Chief Ship Surveyor

6/7/11

Received from Chief Ship Surveyor

VESSEL'S NAME

Skel S.S. Mallina

Rpt.

Bsb.

No. 5221<sup>a</sup>

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage

This vessel is classed, subject to some damage sustained through striking a wharf being made good at the first available opportunity.

The Brisbane Surveyor now reports that has examined the vessel as far as practicable afloat after grounding, and he is of opinion that no material damage had been sustained, but he recommends that she should be dry docked at the first available opportunity.

It should be observed that the classification of this Company's Steamers is not maintained in the Society's Register.

It is submitted action might be deferred.



© 2008  
RBT  
6/7/11

Lloyd's Register  
Foundation

W1529-0078