

1

Celtic Star

Sent to Chief Surveyors

26.6.18

Received from Chief Surveyors

VESSEL'S NAME

Steelss Lamana

Report

Sik

No. 17314

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due

The class of this vessel is subject some damage to plating, framing & sustained this launching being permanently repaired at the first convenient opportunity.

The downton pump has been dispensed with for the duration of the war, as approved.

❖ 100A-1 (Steel) Awning Dk with foreboard } subject &c
2 Dks (Steel) & Awning Dk (Steel)

Cell D.B. a 128' u E 21' f 172' 973C. F.P.T. 32C. A.P.T. 9C.

FK. 6 BH. Cen. Lugs are P. F. a Awning Dk 50'

26.6.18



© 2019

Lloyd's Register
Foundation

W153-0069