

Did the Surveyor examine the safety valves


and their fastenings of the Main Boilers?

, and of the Don

June 66026

Submitted this Report be attached to
 Entry Report - when received

J. J.
 11.5.14.



Lloyd's Register
 Foundation

W1535-0095

Examined... Found all in order.