



600,11,12

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

S/S "Moreno."

Report

B.A.S.

No. 4088 A.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92)

Nature of Survey

Screwshaft.

When due

9.13.

The first biennial screwshaft survey became due in September, and the usual notice was sent to the owners

The Buenos Aires surveyors now write to say ~~that~~ the (owners') manager has informed them that the Company has no further interest in maintaining the class in this Society's Register Book.

Submitted the class be withdrawn and three dots inserted, indicating withdrawal at owners request.

Withdraw class,
Insert (...).

(2)

16.12.13

JWR.

Col. Li

JM



© 2020

W1541-0106

Lloyd's Register Foundation

if so, what alteration is suggested to be made in the existing classification and notification of this survey, 1,11, or "to remain as now classed in the Register Book without fresh record of Survey as classed and notified, 1,11, and the notations of ss No. 1-11 and ptND11, &c."