

Chief Ship Surveyor 15.5.14

Received from Chief Ship Surveyor \_\_\_\_\_

NAME Steel 1/2" Normandy Rpt. Sou No. 8978

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*

Survey Condition

This vessel has been examined in drydock and the bottom cleaned and coated. Some indents in the bottom, due to the vessel lying aground, have been faired in place, and a number of leaky rivets renewed and the landings and butts recaulked where leaking.

It is submitted the vessel appears worthy to remain as classed with record of survey 5.14, as recommended.

100A1 "with freeboard"

5.14 Sou

"for English Channel Service"



© 2020

Lloyd's Register  
Foundation

19.5.14.

W1544-0089