

Report of Survey for Repairs, &c., of Engines and Boilers.

FRI. MAY. 15. 1914

Date of writing Report 13th May 1914 When handed in at Local Office 14th May 1914 Port of Southampton

No. in Reg. Book. 679 Survey held at Southampton Date, First Survey 29th April Last Survey 7th May 1914

on the Machinery of the Wood, Iron or Steel S.S. "Normandy" Master H. J. Swan

Tonnage { Gross 618 Vessel built at Hull By whom Earle's Co. When 1910 MONTH 7
Net 251 Engines made at Do By whom Do When 1910

Registered Horse Power 82 Boilers, when made (Main) 1910 (Donkey) ✓

No. of Main Boilers 2 Owners London & S. Western Rail. Co. Port Southampton Voyage French ports

No. of Donkey Boilers ✓ If Surveyed Afloat or in Dry Dock No. 2 dry dk.

Steam Pressure—
in Main Boilers 16.5
in Donkey Boilers ✓

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. of Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of M.B., if any).
<u>+100 A1</u> <u>with fresh and</u> <u>11.13</u> <u>for English painted service</u>		<u>+L.M.C. 7.10</u> <u>11.13</u>

Last Report No. _____ Port _____

Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of damage (the cause of which must be stated) should be separated from repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ✓ Was a damage report made by anyone else? If so, by whom? ✓

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " " " " ✓

If this was not done, state for what reasons? Not due for survey

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? No To what pressure were they afterwards adjusted under steam? Not adjusted

Did the Surveyor examine the Safety Valves of Donkey Boiler? ✓ To what pressure were they afterwards adjusted under steam? ✓

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? No , and of the Donkey Boiler? ✓

Did the Surveyor examine the drain plugs of the Main Boilers? No , and of the Donkey Boiler? ✓

Did the Surveyor examine all the mountings of the Main Boilers? No , and of the Donkey Boiler? ✓

Has screw shaft now been drawn and examined? No Is it fitted with continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

Has shaft now been changed? No If so, state reasons ✓

Is the shaft now fitted new? No Has it a continuous liner? ✓ or two liners? ✓ or is it without liners? ✓

State the distance between ligament vites of stern bush and top of after bearing of screw shaft? 1/8"

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? Complete.

Propeller and sea-connection fastenings examined and found in order.

General Observations, Opinion, and Recommendation:— This vessel's machinery, so far as
State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,11, B.&M.S. 9,11, or L.M.C. 9,11, 140 lb., F.D., &c.)
seen, is in safe working condition and eligible, in my opinion, to remain as
classified, without further record of survey.

Survey Fee (per Section 28) £ Fees applied for 19
Special Damage or Repair Fee (if any) £ Received by me, R. Elliott
(per Section 28.)
Travelling Expenses (if chargeable) £

Committee's Minute as now FRI. MAY. 22. 1914 TUE. MAY. 4. 1915

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*It is submitted that
this vessel is eligible to
remain as CLASSED*

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

*S/P
20.5.14*

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020

Lloyd's Register
Foundation