

sm.6.14

1

Sent to Chief Surveyors 29. 5. 23.

Received from Chief Surveyors

31 MAY 1923

VESSEL'S NAME

s.k. "Imbrim".

Report

Don.

No. 86684

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

Screw shaft

When due

3. 23.

The Examination of the Screw shaft became due in March last.

In reply to the usual notice the Owners have informed the Bordeaux Surveyors that the vessel was transferred to the Bureau Veritas last year when taken over by them.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof, indicating that the class has been withdrawn at the request of the Owners.

Withdraw class.
Insert ...

Cmd. T.D.
29/5/23.



© 2020

Lloyd's Register
Foundation

W1544-0112