

total capacity tons. FPT tons; APT tons; MI feet tons.  
N.B.—All alterations in the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler spaces.

CHARACTER.  
for Special Survey.  
Date of last Survey and of  
Periodical Surveys.

Years  
Assigned  
now  
expired  
(1)

5m.6.14

16 NOV 1920

sent to Chief Surveyors 13. 11. 20

Received from Chief Surveyors

VESSEL'S NAME

s/s "North Vancouver Ferry No 3" Report Don

No. 83690<sup>a</sup>

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

Limit on forward screw shaft, to examine, will expire in February 1921.

The Owners' Superintendent has informed the Vancouver Surveyors that it has been decided to withdraw the vessel from class, as they do not wish to continue holding periodical surveys in accordance with the Rules.

It is submitted the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof indicating that the vessel's class has been withdrawn at the Owners' request.

Withdraw class.  
Insert . . .

DRK

JWD

13/11/20

M



© 2021

Lloyd's Register  
Foundation