

of Feed pumps 2 Diameter of ditto 4 1/2 Stroke 6 Can one be overhauled while the other is at work
1 ✓ Diameter of ditto 5 Stroke 10 Can one be overhauled while the other is at work

S.S. "Plessis"

Qbc report
No. 1273.

~~the boiler~~

The boiler has been taken from this
vessel & fitted on board the screw ferry
"Hamer Louis Dollich", built 1938, at Langon.

Q. Montreal report No. 4706

Boiler plan transferred to that
vessel

ates of examination of completion of fitting of Sea Connection

the Screw Shaft Tunnel watertight

Yes ✓

Is it fitted with a watertight door

No ✓

worked from

Lloyd's Register
Foundation

W1551 0026

Boiler transferred