

2m. 3. 10.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME STEEL S.S. "LAKE GITANO" Report Detroit No. 216**For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey _____

When due _____

❖ 100 A. 1. (steel)

1 Dk. (steel) 2 hrs beams.

Cell DB 204' 472t. DTA 89t. FPT 72t APT 107t.

PK. 4 BH ptcm A.R.C.P. P25' B64' F23'

It is concluded the bottom ^{is not better "like original"} has not been cemented in way of oil tanks, but the Surveyors should be requested to state if this is so, & also to state whether the oil fuel carried in Deep tanks, Aft Peak & Double Bottom is intended for burning or as cargo.

© 2021
AEB
15.10.19

b100-5519