

1

Sent to Chief Surveyors

23.3.16.

Received from Chief Surveyors

VESSEL'S NAME

s/k. "Plough"

Report

Low.

No. 48750

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Screw shaft

When due

1.16.

The examination of the screw shaft became due in January last.

In reply to the usual notice the Owner now states that the vessel is in the Admiralty Service & he has no wish to keep up the vessel's classification.

It is submitted that this vessel's class be omitted from the Register Book at the next reprint.

JWD

23/3/16

C.F.



© 2021

Lloyd's Register
Foundation

W 1557-0003