

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of New York

No. in Reg. Book 81008 Survey held at on the Wood, Iron or Steel Date, First Survey... Last Survey... 19... (No. of Visits)

S. S. "PROVINCETOWN" Master

TONNAGE:- Built at Groton Conn By whom Groton Iron Works When 1920 9

GROSS 7000 6200 Owners U.S. Shipping Board Port belonging to New York

UNDER DK. 5702 Owners' Address... (if not already recorded in Appendix to Register Book)

NET 3805 Surveyed Afloat or in Dry Dock? Name of Dock? Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons. } CHARACTER, * for Special Survey, Date of last Survey and of Periodical Surveys.

Yard Assigned now expired Machinery and Boiler Surveys (including date of N.B., if any).

LMC 920 Fitted for 9-20

Shelter deck with fld. Plate 1500

Society's Freeboard (if assigned) as painted on Ship and now verified

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

AIN

See copy of letter attached, dated 27th May, 1921, received from the United States Shipping Board requesting the withdrawal from class.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.) When put on, Month Year
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Boats
Waterways	State if Tanks now tested	Scuppers	Masts, Yards, &c.
Coamings	Bulkheads	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Beams & Fastenings	Ceiling	Hatches	Sails
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	Equipment letter
Caulking of ditto	Rudder	Caulking ditto	Anchors, No. of
Rivets	Steering gear and its connections	Treenails ditto	Cables (State if now ranged)
Breasthooks & Crutches	Windlass	Breasthooks & Stemson ditto	length (on board) size
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Rule length size
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	Hawser & Warps
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Standing & Running Rigging
Floors		Stringers, Clamps & Shelves ditto	
Keelsons		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 28)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute New York JUN 7 1921

Character Assigned Withdraw class & insert (...)

Surveyor to Lloyd's Register of Shipping. General Committee. Thursday 30th June 1921. American Committee's decision confirmed

If so, is the Report sent home, or when will it be sent?

The Surveyor is requested not to write on or below the space for Committee's Minute.

Is Certificate required? If so, to be sent to

7800-0087