



Lloyd's Register of Shipping,
324 Bourse.

Phone Lombard 3543.

PHILADELPHIA, November 7th, 1912.

LLOYDS REGISTER
LONDON
REC'D 13 NOV 1912
ANSR 26

M. Sir:

In Reply to your letter of the 29th of October regarding the First Entry of S/S "RAYO" No. 1943, I have to state that the bulb angles for the bilge and side keelsons are .50" and not .45" as stated on report.

The ordinary bulb angle frames are .43" as reported.

I enclose sketch showing section of this bulb which are special sections rolled for these vessels.

Trusting this explanation will be satisfactory.

I am, Sir,

Your obedient Servant,

David Millar

The Secretary,
London.

(One enclosure.)



© 2020

Lloyd's Register
Foundation

W1564-0042

Referred to the Chief Ship Surveyor.

NOV 18 1912

C.B.

(.ethacilone eno)

.ytatecees eni
.nohnoil

.lonh credent zelant

I am, Sir,

.betropes as "Ed. the samet elgna dind ytambro ent
ere hoinw dind alnt to poltosee gnlwona notake eecilone I
.elaeew eent tot bellot enoltosee laioeqe
"ytatecees eni de llw poltseelqex alnt gnlteart
betropes as "Ed. the samet elgna dind ytambro ent
ere hoinw dind alnt to poltosee gnlwona notake eecilone I
.elaeew eent tot bellot enoltosee laioeqe
"ytatecees eni de llw poltseelqex alnt gnlteart

Yrs. M.



© 2020
Lloyd's Register
Foundation