

Loss Crew Space  
Loss above Crown  
Engine Room

**COPY.**

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

19th October, 1920.

Dear Sir,

With reference to Glasgow report No.40312 on the steamer "CHANTALA", I shall be obliged if you will ascertain from the Surveyors and let me know whether the stiffeners on the collision bulkhead are spaced 24" apart.


I am, Dear Sir,

Yours faithfully,

Secretary.

The Secretary.

GLASGOW.



© 2020

Lloyd's Register  
Foundation

W157-0043