

Received from Chief Surveyors _____

to Chief Surveyors _____

SEL'S NAME *Wood 5 Mast. Str. "Bianca"* Report *Sea* No. *1231*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

REG. S. S. SURVEY PARTLY HELD.

When proposed to be completed *Vessel laid up*
 9. 23

tion of Survey held, &c.,

A special survey equal to a H.T. survey to be held at 4 + 8 years from date of build.

*One bower anchor + 90 fms. of cable of proper size weight & test to be supplied
 Remaining bower anchors to be replaced by anchors of proper weight & test.*



© 2021

Lloyd's Register Foundation

W1571-0013

*G.S.
 16.2.24*