

23 SEP. 1921

Sent to Chief Surveyors 22. 9. 21.

Received from Chief Surveyors _____

VESSEL'S NAME Wood 5 Mast. Sr. "BIANCA". Report Sea. No 908**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____ Equipment. _____ When due _____

The Dunedin Surveyor should be advised that the bower anchors on board this vessel require to be replaced by anchors of proper weight and test as required by Table 30, letter "V", and that if stockless anchors are supplied these should be increased $\frac{1}{4}$ th. in weight above that given in Table 30, as compensation for dispensing with stocks.

Mr M. J. Ashie
Dunedin
Ack'd to Sea.

J. G. [Signature]



© 2021
22. 9. 21.

Lloyd's Register
Foundation
W1571-0022