

Chief Surveyors

Received from Chief Surveyors

NAME Wood S. "BIANCA"

Report Sea.

No. 908.

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Survey

When due

This vessel was originally intended to be fitted as a motorship, but was converted into a five masted schooner.

The Three Bower Anchors require to be replaced with others of correct weight and test as required by table 30.

12 A. 1. "Salted"

2 Dks.

A9C.P. P50', F35'

} Subject to a special survey equal to a half time  
 } survey at four & eight years, & also subject to  
 } Bower Anchors being replaced by others of correct weight  
 & test.

M

at B.

11-2-20



© 2021

Lloyd's Register  
 Foundation

5200-1E51M