

of Aster.

is submitted the Middlesbro' Surveyors be informed
concluded that a bucket & rod for the lubricating pump,
7/16" x 1/2" valve springs of each size have been placed on board
here, but as this is not reported they should state if true.
They should also state whether the screw shaft
is fitted with a continuous liner.

C L &

All on board

See Mdb ltr 15/5/20 4/5/20

JWD

Lloyd's Register
Foundation

W1571-0164

The double reduction gear, shafts and propeller shaft have been