

regret that this mistake was not observed before

## Lloyd's Register of British & Foreign Shipping.

Reference

E.

Royal Bank Buildings,  
28, Constitution Street,

Leith, 11<sup>th</sup> June 1902

LLOYD'S REGISTER  
LONDON.

REC<sup>d</sup> 12 JUN 1902

ANS<sup>d</sup>

The Secretary,  
London,

Sir,

In reply to your letter of 11<sup>th</sup> June 1902 regarding the s/s. "Magagan" I beg to state that the shafting was contracted for about June 1901. I regret to find that an error has occurred in reporting the screw shaft, the lines is all in one length, without joints the centre being filled with non-collapsible material.

I am, Sir

your obedient servant  
Thomas Field



© 2020

Lloyd's Register  
Foundation

W1575-0091



Referred to the Chief Engineer Surveyor.

*C.D.*

112 JUN. 1902

Also for Mr. Hill to note.

*C.D.  
12.6.02*



© 2020

Lloyd's Register  
Foundation