

Lloyd's Register of British & Foreign Shipping,

Maritime Buildings,

East Dock Street,

LLOYD'S REGISTER
LONDON.

REC^d

12 JUN 1902

ANS^d

Dundee, 11th June 1902

Sir,

In reply to your letter of the 10th inst respecting the liner on the tail shaft of the steamer "Maragan", Dundee report No 6834; I beg to state that this shaft was made at the Life Forge, Kirkcaldy, under the survey of the Leith Surveyors, was forwarded direct from Kirkcaldy to the shipyard at Frangemouth, and was therefore not seen by me. I was informed by the Builders (Messrs Cooper & Greig) that the liner on this shaft was to be continuous, and they now state that a continuous liner was fitted.

From this it would appear that the Leith Surveyors are in error in stating that two liners are fitted and regret that this mistake was not observed before forwarding my report.

I have communicated with the Leith office and received the following wire in reply. "Maragan liner one length filled noncorrosive material regret error - Field."

I am, Sir,

your obedient servant.

Wm Morrison

The Secretary,
London.

W1574-0002

Referred to the Chief Engineer Surveyor.

280

12 JUN 1902

Also for Mr. Hill to note.

*CMS
12.6.02*

SLM



© 2020

Lloyd's Register
Foundation