



Lloyd's Register of British & Foreign Shipping.

97 & 98, Scottish Provident Buildings,

Donegall Square, West,

Belfast, 1st February 1911LLOYDS REGISTER,
LONDON.

RECORDED 2 FEB 1911

ANSR

The Secretary,
London.

Sir,

In reply to your letter of yesterdays date, having reference to the FE Rep't by 01 on the H. "Lachsen"; I beg to state that the frames in way of double bottom were .46 in thickness and there were six $1\frac{1}{8}$ " rivets in each frame space in the landing edges, making the spacing 4" instead of $4\frac{1}{2}$ " as reported; & the proportion of Depth to Length to Bridge Deck. is 10.87.

I regret these items were incorrectly reported.

With reference to the forecastle stringer angle, the thickness as reported was measured from the ship, and in view of the complete steel deck and extra thickness of stringer plate is submitted for approval.

I am, Sir,

Your Obedient Servant,
P. H. Kendall

W1574-0152

© 2020
Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor.

as
FEB -2 1911

RM 3/2/11

AN



© 2020

Lloyd's Register
Foundation

Received by
VESSEL'S
The
Nature of

Sm. 3.10.

Leo Cray