

0,18,

to Chief Surveyors _____

Received from Chief Surveyors _____

SHIP'S NAME _____ Steel S.S. "SARCOXIE". Report Phl. No.3234

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

ature of Survey _____

When due _____


The chain cables are of cast steel tested as required.

100 A.1. (Steel).

2 Dks. (Steel) & Webframes.

Cell DB 279' 1380t. MT 24' 748t. FPT 144t. APT 100t.

EK. 8 BH. Cen. A. & C.P. P39', B122', F43'.



29. 5. 19.

Detailed approved plans not received.

See Enquiry re deep tank stiffeners in report of S.S. Sabala

*S.O.
19.6/19*

R

*See Letter
30.7.19*

Lloyd's Register
Foundation