

COPY.

# Lloyd's Register of Shipping.



Port BOMBAY.

1st JUNE 1942.

This is to Certify that I have

Surveyed the

temporary repairs to No. 2 tank top of the Steel

Screw Steamer "CLAN MACWHIRTER" 5941 tons gross of Glasgow,

as she lay afloat in Alexandra Dock, Bombay,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be continued in her

present class viz :- **100 A1** without fresh record, subject to permanent repairs to No.2 tank top and to shell, framing, etc., in way of No.4 hold port side at first opportunity and to indented topside plating and bulwarks port side of No.1 hold being dealt with.

dry and perishable cargo.  
being fit to carry

*St. John Southwell*  
(Signature)

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—  
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or of the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register Foundation

WIS8 0057

10m 2,38

Telling Expenses (if chargeable)

10/-

Received by me,

19