

Boilage
Crew Space
Crown of
21.48 Length on deck from after part of stem to fore part of
120 to Owners, Lucata

2m, 12.3.

Received by Chief Ship Surveyor 21.1.04

Received from Chief Ship Surveyor

VESSEL'S NAME *St. S. S. "Sars"*

Report *Gen* No. 3019

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey *First entry.*

It is submitted that before this case reaches the consideration of the Committee it should be pointed out to the Genoa Surveyors that according to their first entry report the vessel requires to be supplied with a topline of 75 fathoms $7\frac{1}{2}$ " and a hauler of 90 fathoms $5\frac{1}{2}$ ". They should be requested to state whether this have been placed on board. They should at the same time state the size of the mudder head and heel which they have omitted from their report.

*Lr. to Genoa
21/1/04*

*C.A.P.
21/1/04*



© 2021

Lloyd's Register Foundation

W1583-0042

Quarter, 'tween Dks, " "						Forecastle Deck Stringer Plate, breadth & thickness
in Hold						" Angle on ditto

Book).
1.00
2.00
Dock
with Flat
Beams
of Be
es in Ship
7x1
30
4
30
5/2
254
etc
Inches
Ship
in S
7.6
7.6
3/4 6
7/4 6
2/4 6
3/4 6
2/4 6
2/4 7
4 5
7.6
27/4 6
6