

yors 7.8.18

Received from Chief Surveyors

10 AUG 1918

1E S/Ss Montserrat II

Report

Rcl

No. 1470

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case at the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

When due

The Bilbao Surveyors should be informed of the Barcelona Surveyor's remarks and requested to ascertain from the Owners what definite arrangements they propose making for replacing the centre portion of the watertight bulkhead or fitting a watertight door.

L. M. J. Ashill
Banco Bco. 10.8.18



9. 8. 18

© 2020

Lloyd's Register

401586-0249