

1

Sent to Chief Surveyors 23/11/20

Received from Chief Surveyors _____

VESSEL'S NAME

s/s "Spider"

Report

LonNo. 83461^a**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Boiler

When due

10.20.

The boiler survey became due on 10.20, no part has been held.

The Owners now request that the vessel's class be withdrawn from the Register Book.

It is submitted that the class be withdrawn & three dots inserted in lieu thereof indicating that the class has been withdrawn at the Owners request.

Withdraw class
Insert . . .

NRSL



Lloyd's Register
Foundation

W1588-0091