

~~D. H. B. B. B.~~

10 MAR. 1923

sent to Chief Surveyors 8.3.23. Received from Chief Surveyors

VESSEL'S NAME s.k. "Star Divine" Report No. 86+17^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey / When due

The examination of the screw shaft became due in 7.21.
 A new screw shaft, it is stated, was fitted to the vessel in 5.21 but not seen by a Surveyor to the Society.
 The Aberdeen Surveyors were requested to verify the fitting of this shaft & if satisfactory the vessel would be eligible for a record of NS 5.21. This has not yet been done.
 The Owner now states that it is not his intention to continue the class of the vessel.
 It is submitted that the vessel's class be withdrawn from the Register Book & three dots inserted in lieu thereof indicating that the class has been withdrawn at the Owner's request.

Withdraw class
Insert ...

M. / Paul / J.W. 8/3/23

