

COPY.

GLASGOW

GLASGOW REPORT No. 59568

5th April, 1938.

Dear Sirs,

"CORINALDO".

With reference to the survey which has recently been held here on the above vessel, I beg to acquaint you that the Committee have had before them at their Meeting to-day the Surveyors' reports from which it appears that the 2nd Special Survey No. 1, which became due at the end of February last, has been further advanced on the hull and machinery and the following now remains to be done to complete the inspection in question, viz:-

HULL:

Vessel to be drydocked;  
Chain cables to be ranged and examined;  
Chain locker to be examined;  
Anchors to be examined;  
Nos. 1, 4 & 5 D.B. Tanks to be examined internally;  
Oil Fuel Bunkers (P. & S.) to be examined internally;  
Oil Fuel Bunker (Port) to be tested.

MACHINERY:

Sea connections and electrical installation to be examined.

I am, Dear Sirs,

Yours faithfully,

Messrs. Donaldson South American Line, Ltd.,  
14, St. Vincent Place,  
GLASGOW, C.I.

(Sgd.) P.L. WARLOW

Lloyd's Register  
Secretary to the  
Glasgow Committee.  
Foundation

W160-0006