

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "CORINALDO"Report J.H.No. 17882.**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

When due _____

The Donington pump has been dispensed with for the present but it is
Concluded the Owners are agreeable to fit same when required

✠ 100. A-1. (Steel) "Shelter DK with foreboard"

2 Dks (Steel) & Shelter DK (Steel). 3rd DK (Steel) in forward hold

Cell IB 355' 1107t ———— F.P.T. 96t, A.P.T. 50t.

FK, 6BK to Shelter DK, 1BK to upper DK, fit Cam, Rlyths Av CP.

Date of build 2,21.

See letter
15.5.21

© 2019

H

19.5.21

It is Concluded the Shelter and upper DK plating is increased in way of the openings
as approved but the Surveyors should be requested to state if this is so
they should also be requested to state the water capacity of the oil fuel tanks in the Machinery Space
if these tanks may be used for water ballast

2700-0910