

REC'D NEW YORK MAR 18 1938 113

WESTINGHOUSE
ELECTRIC & MANUFACTURING COMPANY
LESTER BRANCH P. O., PHILADELPHIA, PA.



March 17, 1938

Lloyd's Register of Shipping
17 Battery Place
New York City, New York

Attention: Mr. J. Heck, General Engineer

Dear Mr. Heck:

Section 2, paragraph 11, of your 1937-1938 Edition of Rules and Regulations specifies that a turbine driving a direct-current generator arranged for parallel operation be provided with a trip switch on the emergency governor to open the circuit breaker when the emergency governor functions.

In the interest of simplification, we request that consideration be given to eliminating this requirement in cases where the circuit breakers are provided with reverse current trip, as specified in Section 3-A, sub-paragraphs (e) and (f). The reverse current trip makes it unnecessary to have the emergency governor trip switch, and its elimination in such cases would avoid an undesirable complication.

Very truly yours,

Marine Department

W. E. Thau/hgd

Every House
needs
Westinghouse



© 2019

Lloyd's Register
Foundation
0160-0157