

ut to Chief Surveyors

2/5/12

Received from Chief Surveyors

SSEL'S NAME

*Ated' Juss' row*

Report

*B A*

No. *3400*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey

When due

The Buenos Ayres Surveyors recently stated that this vessel had been in dry dock at their port, but they were informed verbally by the Government Officials that it was not intended to retain her classification in the Society's Register, and consequently no survey was held by the Surveyors.

It is submitted the vessel's class be omitted from the reprint of the Register Book.

*E. E. J.*  
*J. R. R.*

*M*

*2/8/11*

*2/5/12*

*2021*



Lloyd's Register  
Foundation

W1602-0012