

Received by Chief Ship Surveyor 27.4.14

Received from Chief Ship Surveyor _____

VESSEL'S NAME Screw Lug Cargo Launch "Tofo" Rpt. Ply No. 5533

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry

It is submitted before this case receives the consideration of the Committee, the Plymouth Surveyor should be requested by wire to state whether the two elm stringers 5 x 3, shewn on the midship section, have been fitted; also whether hanging knees have been fitted to the deck beams, and if so, to state their number. He should at the same time be requested to state whether the nature of the examination of the vessel, which he was able to make during the time the vessel was under construction, was such, in his opinion to ^{entitle vessel to the} ~~enable~~ the Special Survey mark ~~to be given.~~

Yel shi 28.4.14

28.4.14.



© 2021

Lloyd's Register Foundation

W1603-0208