

7 DEC 1914

to Chief Surveyors 7, 12, 14

Received from Chief Surveyors _____

SEL'S NAME Wood's Topo Report Ply. No. 5335**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor Expt When due _____

Lloyd's Agent at Coquimbo should be asked to state if the Anchor & Chains have been examined & the marks thereon compared with the Certificates of test, & if so to forward particulars of the anchor & chains, test marks &c to this office.

L. M. Hastie
 Broker & Co
 L.A. Astor
 Dec 10/14 8.12.14



© 2021

 Lloyd's Register
 Foundation

W1603-0216