

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of London Last Survey... 19...

No. in Reg. Book. Survey held at 25625 on the Wood Iron or Steel S.K. Vesta Date, First Survey... Last Survey... Master Cochrane & Sons

TONNAGE: 240 Built at Selby By whom Cochrane & Sons When 1905 5

GROSS 240 Owners Letty Bros Mgrs Port belonging to Grimby

UNDER DE. 222 Owners' Address See memo to dated 14/5/23

NET 100 (if not already recorded in Appendix to Register Book). Name of Dock... Destined Voyage...

Surveyed Afloat or in Dry Dock? W/B=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

Last Report, No. 12959 Port Gms

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey, Date of last Survey and of Periodical Surveys.	Year Assigned how expired	Machinery and Boiler Survey (including date of N.B., if any).
+100A1		+LMC 4.19
Stn. Gauges 9.22		BS 9.22
SS Gms No 3-4.19		TS 4.19

Society's Freeboard (if assigned) as painted on Ship and now verified... ft... ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

PRIMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
State if Tanks now tested	Engine Room Skylights	Copper, or Y.M. of Wood Vessels (State if on Feet.)	When put on, Month Year
Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats	
Ceiling	Scuppers	Masts, Yards, &c.	
Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained	
Rudder	Hatches	(State if wedges removed)	
Steering gear and its connections	Planking of Wood Vessels	Sails	
Windlass	Caulking	Equipment letter	
Have Pumps now been examined and found efficient?	Treenails	Anchors, No. of	
Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)	
Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	length size	
Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Rule length size	
	Ditto ditto at other places ditto	Hayser & Warps	
	Stringers, Clamps & Shelves	Standing Running Rigging	
	Salting (State if examined.)		

General Observations, Opinion as to Class, Recommendation, &c. State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example: "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Fees applied for,	Received by me,
Survey Fee (per Section 20) £	19
Special Damage or Repair Fee (if any) (per Sec. 20) £	19
Travelling Expenses (if chargeable) £	
Land Surveyor's Fee (if any) £	

Committee's Minute... Character Assigned... Withdraw class... Surveyor to Lloyd's Register of Shipping... General Committee... Thursday 25th April 1923... Classing Committee's... Lloyd's Register Foundation