

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.


8th March, 1910.

Dear Sir,

H. I have to acquaint you that I am informed by the Director of Marine that the steamer "TROJAN" is at present in dock at Lagos undergoing overhaul and survey. According to the Society's Rules under which this vessel is classed the Special Survey No.1 became due in November last and as this Society has no Surveyor stationed in the vicinity of Lagos the Committee will be obliged if you will kindly appoint a competent and independent Surveyor to undertake the inspection. For the guidance of the gentleman you may be good enough to appoint I enclose herewith sample reports together with an abstract from the Society's Rules setting forth the requirements of the inspection. Forms for reporting the survey are also forwarded and I shall be obliged if you will kindly return the same to this Office in due course.

As regards the survey of the engines and boiler I may say that the boiler safety valves will require to be adjusted under steam to a safe working pressure of not exceeding 130lb per square inch. I may add that all fees and expenses in connexion with this matter must be paid by the Owners or their Representatives and should accordingly be charged by

4th n
A: Su
M
(inclu
+L
36 an
Vess
1
here
W160510154 1/2
ing Rigging...



you to them.

I am, Dear Sir,

Yours faithfully,

Secretary.

J.R.U.Little, Esq.,
Lloyd's Agent,
LAGOS.



© 2021

Lloyd's Register
Foundation

W1605-0154 2/2