



Lloyd's Register of British & Foreign Shipping,

97 & 98, Scottish Provident Buildings,

Donegall Square, West,

Belfast, *2nd October 1909.*

LLOYDS REGISTER,
LONDON.

REC^d 4 OCT 1909

ANS^d

Reference

M

*1 encl / The Secretary.
London.*

Sir,

In reply to your letter of yesterday's date respecting the case of the "T. St. Terona" I beg to state that the after peak tank of this vessel was examined internally and externally in dry dock. before the repairs were put in hand, and was found to be in good condition, the riveting in frames and shell plating was tested and found sound and there were no signs of fracture in frames or shell plating.

It is understood that some additional stiffening was put in this tank in Genoa as indicated in red ink on the sketch enclosed herewith.

I am, Sir,

Your Obedient Servant.

J. H. Kendall.

© 2021

Lloyd's Register
Foundation

W1609-0024

W1609-0028

Deferred to the Chief ~~of~~ Surveyor.


OCT -4 1909.

Also for Mr. S. A. Hill to note.

C. L. Hill
10/10/09
B.

g
2
10
15



© 2021

Lloyd's Register
Foundation