

Is. Verona

It is submitted the Belfast Surveyors should be informed it is understood that the S.S. "Verona" is now in dry dock under their survey. They should be requested to state by return of post precisely the condition in which the stern framing plating and riveting was found by them when surveyed in dry dock before any additions or repairs were put in hand.

Lr Belfast
1/10/09.

B. 1/10/09



© 2021

Lloyd's Register
Foundation

W1609-0027