

Lhol.



Lloyd's Register of Shipping,

3, Steinhoefl,

Hamburg, 2nd March, 1939.

Dear Sir,

The Motorship "DON ESTEBAN" No.73372 in the Register Book, owned by Messrs. Hijos de J. de la Rama y Cia. has recently been under survey in Manila for a broken crankshaft, where it is understood temporary repairs have been effected and which doubtless will already have been reported to London.

A portion of the broken crankshaft has been sent to the Engine Manufacturers, Messrs. Fried. Krupp Germaniawerft, Kiel for examination and an opinion as to the cause of fracture. Messrs. Krupp have now replied to the Owners and have sent to us a copy of their report together with a number of photographs and these we now enclose for your information.

W.S.
I am, Dear Sir,

W.S.
Yours faithfully,

The Secretary,
LONDON.



© 2014 Lloyd's Register Foundation
w161-0016

Referred to the Chief Engineer Surveyor

APR-1942

RJ
3 MAR 1942
Also for Mr. Hillman
J. H. Stoney
Three Star Queen
R. J. Hillman

Mr. George D. Johnson.

Dear Sir,

The Motor Trade Register states
that a G. S. G. & Co. Ltd. have
not a permanent record of not
less than one year's residence in
the United Kingdom, and
therefore need not pay
any stamp duty on the
transfer of their residence
to another place. However,
as they are not permanent
residents, they must pay
stamp duty on the transfer
of their residence to another
place. This is the only reason
why we cannot issue
them a certificate of
non-residence.

With regards, etc.,
Yours very truly,



3, Seinouself,

• 2881, Dorval Bag, Quebec,