

Rpt. 8.

Now Named

(Received at London Office)

No. 87249^a

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 1910 When handed in at Local Office

Port of London

No. in Survey held at Reg. Book.

Date, First Survey

Last Survey

19

32591 on the Wood, Iron or Steel Sc Sr "Sarajevo"

Master

TONNAGE:-

Built at Monfalcone

By whom Capt. Nav. Trastino When 1910

YEAR. MONTH. 2

GROSS 1158

Owners

Lloyd Trastino

Port belonging to Trieste

UNDER DEK 794

NET 527

Owners' Address

(if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet; f

tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 5879 Port TRI

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.	Year and Month when last Surveyed	Machinery and Boiler Surveys (including date of N.B., if any).
* for Special Survey.		
Date of last Survey and of Periodical Surveys.		
+100A1 6.23		THYC 1.22
Shack dk with fba		BS9 22
S.S. Tri No 3-2, 18.		TSS 21.01
S.S. Tri No 1-22.		
For service in the Adriatic		
Society's Freeboard (if assigned) as		
Painted on Ship and now verified		

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Fair'd or Repaired ...								
Fair'd or Repaired in place ...								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dbng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels.
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
Waterways	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Coamings	Ceiling	Scuppers	Boats
Beams & Fastenings	Cement or Asphalt	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	(State which.)	Hatches	Condition, how ascertained
Caulking of ditto	Rudder	Planking of Wood Vessels	(State if wedges removed)
Rivets	Steering gear and its connections	Caulking ditto	Sails
Breasthooks & Crutches	Windlass	Treemails ditto	Equipment letter
Transoms	Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Frames	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Floors	Have Ventilators and their Coamings been examined and found efficient?	Ditto ditto at other places ditto	" Rule length size
Keelsons		Stringers, Clamps & Shells ditto	Hawser & Warps
Stringers		Salting ditto	Standing & Running Rigging
Inner Bottom Plating		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—


State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptnd15, &c."

Survey Fee (per Section 20)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation