

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report..... 19..... When handed in at Local Office..... 19..... Port of..... London.....
No. in Survey held at..... Date, First Survey..... Last Survey..... 19.....
Reg. Book..... (No. of Visits.....)21953 on the ~~Wood, Iron or Steel~~ Twin Sc Sr. "Helouan" Master
TONNAGE:- Built at Trieste By whom Lloyd Austraco When 1912 1
GROSS 7456 Owners Lloyd Triestino Port belonging to Trieste
UNDER DK. 5986
NET 3009 Owners' Address
(If not already recorded in Appendix to Register Book).Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=CellDBorDBa feet; uE&B feet; f feet; Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons precisely as in Register Book & Supplements).N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 5905 Port TRI.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

CHARACTER.
* for Special Survey.
Date of last Survey and of Periodical Surveys.
Years Assigned now expired.
Machinery and Boiler Surveys (including date of N.B., if any).
+100A1 823 TLMC 419
Awng dk with fbd BS 9.22
ss Tri No 2 19 753 22 CL
Trieste & Alexandria. Fitted for oil fuel 112 F Below 150°F
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

DISCLOSED
SECTION.

No. 120

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
Waterways	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month
Coamings	Ceiling	Scuppers	Boats
Beams & Fastenings	Cement or Asphalt	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	(State which.)	Hatches	Condition, how ascertained
Caulking of ditto	Rudder	Planking of Wood Vessels	(State if wedges removed)
Rivets	Steering gear and its connections	Caulking ditto	Sails
Breasthooks & Crutches	Windlass	Treenails ditto	Equipment letter
Transoms	Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Frames	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	" length
Floors	Have Ventilators and their Coamings been examined and found efficient?	Ditto ditto at other places ditto	" Rule length
Keelsons		Stringers, Clamps & Shells ditto	Hawser & Warps
Stringers		Salting ditto	Standing & Running Rigging
Inner Bottom Plating		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—


State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register
Foundation
11617-0098