

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 19... When handed in at Local Office 19...

Port of London

DISCLOSED  
BOX No. 10No. in Survey held at  
Reg. Book.

Date, First Survey

Last Survey

19

30608 on the ~~Wood, Iron or~~ Steel Sc Sr Praga

Master

TONNAGE:-

Built at Trieste

By whom Lloyd Austraco When 1908

MONTH

GROSS 3840

Owners

Lloyd Triestino

Port belonging to Trieste

UNDER DK. 2822

Owners' Address

NET 2226

(if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&amp;B

feet

feet

total capacity tons. FPT tons; APT tons; MT tons

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 5627 Port TRI.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of  
Periodical Surveys.Years  
Assigned  
now  
expiredMachinery and Boiler  
Surveys  
(including date of N.B., if any).

T100A1

Sparak

1122

TAMC 2,21

BS 11,22

TS 11,22CL

S.S. Tri No 3-7,21.  
Society's Freeboard (if assigned) as  
painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

## SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ...								
Removed and Faired or Repaired ...								
Faired or Repaired in place ...								

## PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	When put on, Month Year
Waterways	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
Coamings	Ceiling	Scuppers	Masts, Yards, &c.
Beams & Fastenings	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained
Outside Plating	Rudder	Hatches	(State if wedges removed)
Caulking of ditto	Steering gear and its connections	Planking of Wood Vessels	Sails
Rivets	Windlass	Caulking ditto	Equipment letter
Breasthooks & Crutches	Have Pumps now been examined and found effi-	Treenails ditto	Anchors, No. of
Transoms	cient?	Breasthooks & Stemson ditto	Cables (State if now ranged)
Frames	Have Sluice Valves now been examined and found	Transoms, Pointers, & Crutches ditto	" length size
Reverse Frames	efficient?	Timbers of Frame at openings ditto	(on board) size
Floors	Have Watertight Doors now been examined and found	Ditto ditto at other places ditto	" Rule length size
Keelsons	efficient?	Stringers, Clamps & Shelves ditto	Hawser & Warps
Stringers	Have Ventilators and their Coamings been examined	Salting ditto	Standing & Running Rigging
Inner Bottom Plating	and found efficient?	(State if examined.)	

## General Observations, Opinion as to Class, Recommendation, &amp;c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 20) £

Fees applied for,

Special Damage or Repair Fee (if any) £

Received by me,

Travelling Expenses (if chargeable) £


19

Second Surveyor's Fee (if any) £

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

Lloyd's Register  
Foundation