

Inspected by Chief Ship Surveyor 17.7.08

Received from Chief Ship Surveyor

VESSEL'S NAME Ste. S.S. "Praga"Rpt. Tri No. 1940

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>1/20" less, but compensated by increased thickness of strake above.</u>	
Spar Sheerstrake . .	<u>2/20"</u>	<u>Proportions</u>
Description of Framing:— <u>Deep framing, increased in depth on</u> (viz., ordinary, deep, zed, channel or bulb-angle). <u>account of erections.</u>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\pm$  100 A 1 ("Steel") "Spar Deck" as recommended.

 $\pm$  100 A 1 ("Steel") "Spar Deck".

1 DR (Ste) + Spar DR (Ste - w/o) + deep framing.

W.B = Cee DB a 108' u E 38' f 142' 669t APT 21t

FK 68H Cam. Lloyd's A4CP PVB 246' F65'

The Surveyor should be requested to state the test of the 14" wire hawser.