

S.T. "ALGONQUIN" No.50853 in R.B.

From plans available in this Office it would appear that the accommodation amidships is situated immediately over the cargo oil tanks.

From the First Entry Report it would appear that the cables are not lead sheathed, and when the vessel is examined in accordance with Circular 1994 the cables throughout the vessel and any electrical equipment fitted in the midships accommodation mentioned above should receive special attention *as should cargo pump room lighting arrangements.*

JH

10th March, 1953.

Sa.

ESW



© 2021

Lloyd's Register
Foundation

W1624-0161